

**GOVERNMENT OF INDIA
INFORMATION AND BROADCASTING
LOK SABHA**

UNSTARRED QUESTION NO:3472
ANSWERED ON:15.05.2006
HARINAGAR DOORDARSHAN KENDRA IN BIHAR
Baitha Shri Kailash

Will the Minister of INFORMATION AND BROADCASTING be pleased to state:

- (a) whether Harinagar Doordarshan Kendra in Bihar is not telecasting programmes as per its capacity;
- (b) if so, the reasons therefor; and
- (c) the corrective steps taken by the Government in this regard?

Answer

THE MINISTER OF INFORMATION AND BROADCASTING AND PARLIAMENTARY AFFAIRS (SHRI P. R. DASMUNSI)

(a) to (c): The Low Power TV Transmitter (100 W) [LPT] at Ramnagar (Harinagar) is being manned by skeletal staff who have been provided by way of redeployment as the requisite manpower has not been made available. Transmission is limited to evenings only as the transmitter is operating on low capacity of 75 watt power due to failure of a sub-unit of the transmitter. Action is on the anvil to operationalise it on full power capacity of 100 W.