

**GOVERNMENT OF INDIA
POWER
LOK SABHA**

UNSTARRED QUESTION NO:2495
ANSWERED ON:09.12.2005
KOTA THERMAL POWER STATION
Bishnoi Shri Jaswant Singh

Will the Minister of POWER be pleased to state:

- (a) the reasons for repeated failure of electrical units of Kota Thermal Power Station, Rajasthan;
- (b) whether advance technology is not being utilized in this project; and
- (c) if so, the reasons for continuous decrease in the power production by this Thermal Power Station?

Answer

MINISTER OF INFORMATION & BROADCASTING & MINISTER OF PARLIAMENTARY AFFAIRS (SHRI PRIYA RANJAN DASMUNSI)

- (a) : Repeated failure of electrical units of Kota Thermal Power Station (TPS) in Rajasthan during April, 2005 to November, 2005 was not there.
- (b) : All the generating units installed at Kota TPS are of BHEL make which are being predominantly used in the country.
- (c) : There has been no decrease in actual generation by Kota TPS.